

Addendum, Additions, Corrections & Notes
`Featured Auction` with Live Close
October 10, 2024

Lot 396: ADDENDUM ADDED 9/20/24: Please note that this watch is actually SW-SS, not SW-LS as was erroneously listed. Also, we note that the crown requires some constant upward pressure while the crown is turned to remain in setting engagement and will drop to winding engagement if the upward pressure is released.

Lot 166: ADDENDUM ADDED 9/26/24: Please note that the balance bridge of this watch is missing a screw that secures one of its feet.

Lot 203: ADDENDUM ADDED 9/26/24: A positive update here - after a bit of prodding this chronometer has proceeded to run and exhibit good winding indicator function. Our consignor notes though that this piece has likely not seen any type of servicing in many years so he (and we) very strongly recommend that the movement be serviced prior to additional runnings.

Lot 381: ADDENDUM ADDED 9/26/24: Please note this watch is a recase, and is not an original case as was erroneously catalogued. This is confirmed by the consignor's notes on the piece.

Lot 384: ADDENDUM ADDED 9/26/24: Please note the regulator adjustment screw is not making contact with the regulator needle as there is a bit of open space between these elements. We have not disassembled to inspect whether the regulator spring on the underside of the balance cock is intact and functioning.